

APC SMT2200RMI2U

Written by WebAdmin

Thursday, 15 March 2018 11:10 - Last Updated Thursday, 15 March 2018 11:17



Keluhan : -

Kerusakan umum : Mati, nyala lalu mati, Bunyi terus menerus, tidak bisa charge, tidak backup saat listrik mati, Blinking saat dinyalakan, lampu panel kedap-kedip, Charging tidak bisa penuh

Spesifikasi :

- Brand : APC
- Tipe : Line interactive
- 1980 Watt
- Input connection : IEC-320-C20, Schuko(EU1-16P)

Tipe lain : APC-SMT750RMI2U, APC-SMT1000I, APC-SMT1000RM12U, APC-SMT1500RMI2U, APC-SMT1500i
